

# SEARCHED

Class	Sub.	Date	Exmr.
381	56	11/29	AN
	104	4	"
	106	4	"
	107	7	"
	108	7	"
	102	7	"
	101	7	"
	396	7	"
	15	11/4	"
	16	4	"
381	56, 101, 108, 104	5/4/00	BTP
	updated	11/29/03	BTP
	updated	7/15/02	BTP
	Searched above	9/4/03	BTP
381	83, 93	9/25/03	BTP
381	65	7/5/05	BTP
	updated from	7/5/05	BTP

## INTERFERENCE SEARCHED

Class	Sub.	Date	Exmr.
	Searched above	9/19/02	BTP

## SEARCH NOTES (INCLUDING SEARCH STRATEGY)

Consulted with  
 Ping Lee  
 Consulted with  
 Le-Mei  
 Consulted with  
 F.W. Isen.  
 Discussed the  
 limitation of  
 determining a  
 RMS value for  
 the feedback  
 control signal

11/29 AN  
 11/30 AN.  
 11/17/03 BTP